

2026 年 10 月 吉日

お客様ならびに代理店各位

ReadyToProcess™ ULTA™製品販売終了および後継品に関するご案内

拝啓 貴社、益々ご清栄のこととお慶び申し上げます。平素より弊社製品をご利用いただき誠にありがとうございます。

このたび、弊社 ReadyToProcess™ ULTA™ 製品に関して、下記の通り販売終了および後継品をご案内申し上げます。最も正確な情報につきましては別添の英語版原本もご参照いただきますようお願い申し上げます。

ご質問やご不明な点がございましたら、以下のバイオダイレクトラインまでお問い合わせください。

バイオダイレクトライン（製品問合せ対応窓口）TEL: 03-5331-9336（音声案内②） e-mail: Tech-JP@cytiva.com

この度はご迷惑をおかけいたします。今後とも Cytiva をご愛顧賜りますようよろしくお願い申し上げます。

敬具

Cytiva（サイティバ）

バイオプロセス事業部

法人名：グローバルライフサイエンステクノロジーズジャパン株式会社

記

ポートフォリオ管理の一環として、社内リソースを効率化し、お客様に最高品質のフィルターを提供するため、技術およびサイズが重複するフィルター製品が確認された ReadyToProcess™ ULTA™ 製品を 2027 年 9 月 11 日をもって販売終了させていただきます。

販売終了日まで引き続きご注文可能ですが、本通知以降のご注文に関しては供給可能性を個別に判断させていただきます。

代替品が記載されている製品をご使用のお客様は、同じフィルターメディアを使用し、同等の機能を有する代替品をご使用いただけます。

代替品の記載がない製品をご使用のお客様は、ニーズに適した標準品またはカスタムフィルターについて、バイオダイレクトラインまでお問い合わせください。

その他のフィルター製品ラインは販売終了予定はありません。

販売終了製品		代替品	
製品番号	製品名	製品番号	製品名
12410058	1X CG9202 2X 0.5FT CF RM	8090-2122M	F-RM-KA02-EAV-0.2-RM
12410059	1X CG9204 2X 0.5FT CF RM	8090-2122N	F-RM-KA3-EAV-0.2-RM
12410060	1X CG92H1 2X RM	8090-2122N	F-RM-KA3-EAV-0.2-RM
12410061	1X CG9206 2X 0.5FT CF RM	8090-2122N	F-RM-KA3-EAV-0.2-RM
12410062	1X CG9210 2X RM	8090-2122Q	F-RM-NP6-EAV-0.2-RM
12410063	1X CG9220 2X RM	8090-2122R	F-RM-NP7-EAV-0.2-RM
12410064	1X CG9230 2X RM	8090-2122S	F-RM-NP8-EAV-0.2-RM
12410065	1X GF9602 2X 0.5FT CF RM	推奨代替品についてはバイオダイレクトラインにお問合せ ください。Allegro Ready およびカスタムデザインの製品の 提案が可能です。	
12410066	1X GF9604 2X 0.5FT CF RM		
12410067	1X GF96H1 2X RM		
12410068	1X GF9606 2X 0.5FT CF RM		
12410069	1X GF9610 2X RM		
12410070	1X GF9620 2X RM		
12410071	1X GF9630 2X RM		
12410072	1X GF0102 2X 0.5FT CF RM		
12410073	1X GF0104 2X 0.5FT CF RM		
12410074	1X GF0106 2X 0.5FT CF RM		
12410075	1X GF01H1 2X RM		
12410076	1X GF0110 2X RM		
12410077	1X GF0120 2X RM		
12410078	1X GF0130 2X RM		
12410079	1X GF0202 2X 0.5FT CF RM		
12410080	1X GF0204 2X 0.5FT CF RM		
12410081	1X GF0206 2X 0.5FT CF RM		
12410082	1X GF02H1 2X RM		
12410083	1X GF0210 2X RM		
12410084	1X GF0220 2X RM		
12410085	1X GF0230 2X RM		
12410086	1X GF0502 2X 0.5FT CF RM		
12410087	1X GF0504 2X 0.5FT CF RM		
12410088	1X GF05H1 2X RM		
12410089	1X GF0506 2X 0.5FT CF RM		
12410090	1X GF0510 2X RM		
12410091	1X GF0520 2X RM		
12410092	1X GF0530 2X RM		
12410093	1X HC9202 2X 0.5FT CF RM	8090-2081V	F-RM-KA1-EKV-0.2-RM
12410094	1X HC9204 2X 0.5FT CF RM	8090-2033T	F-RM-KA2-EKV-0.2-RM
12410095	1X HC92H1 2X RM	8090-2033U	F-RM-KA3-EKV-0.2-RM
12410096	1X HC9206 2X 0.5FT CF RM	8090-2033V	F-RM-NP5-EKV-0.2-RM
12410097	1X HC9210 2X RM	8090-2033W	F-RM-NP6-EKV-0.2-RM
12410098	1X HC9220 2X RM	8090-2033X	F-RM-NP7-EKV-0.2-RM
12410099	1X HC9230 2X RM	8090-2033Y	F-RM-NP8-EKV-0.2-RM
12410100	1X SG9202 2X 0.5FT CF RM	8090-2081V	F-RM-KA1-EKV-0.2-RM
12410101	1X SG9204 2X 0.5FT CF RM	8090-2033T	F-RM-KA2-EKV-0.2-RM

販売終了製品（続き）		代替品（続き）	
製品番号	製品名	製品番号	製品名
12410102	1X SG92H1 2X RM	8090-2033U	F-RM-KA3-EKV-0.2-RM
12410103	1X SG9206 2X 0.5FT CF RM	8090-2033V	F-RM-NP5-EKV-0.2-RM
12410104	1X SG9210 2X RM	8090-2033W	F-RM-NP6-EKV-0.2-RM
12410105	1X SG9220 2X RM	8090-2033X	F-RM-NP7-EKV-0.2-RM
12410106	1X SG9230 2X RM	8090-2033Y	F-RM-NP8-EKV-0.2-RM
12410245	1X GF0502 1X CG9202 2X 0.5FT C RM	推奨代替品についてはバイオダイレクトラインにお問合せください。Allegro Ready およびカスタムデザインの製品の提案が可能です。	
12410246	1X GF05H1 1X CG9206 1X 0.5FT C RM		
12410247	1X GF0510 1X CG92H1 2X RM		
12410248	1X GF0520 1X CG9210 2X RM		
12410251	1X GF0502 1X HC9202 2X 0.5FT C RM		
12410252	1X GF05H1 1X HC9206 1X 0.5FT C RM		
12410253	1X GF0510 1X HC92H1 2X RM		
29096239	1MR9102 2X 0.5FT CF RM		
29096772	1MR9104 2X 0.5FT CF RM		
29096785	1MR91H1 2X RM		
29096794	1MR9106 2X 0.5FT CF RM		
29096798	1MR9110 2X RM		
29096802	1MR9120 2X RM		
29096805	1MR9130 2X RM		
80590446	DOMESTIC RTP ReadyCircuits - Filtration		
28925793	DF RTP ULTA NFF capsules and assemblies		
KMPHHC9202HH	ULTA HC RTP 0,2um 2IN HBHB 3pk	KA1EKVP6G	Kleenpak Supor EKV 0,2um
KMPHSG9202HH	ULTA SG RTP 0,2um 2IN HBHB 3pk	KA1EKVP6G	Kleenpak Supor EKV 0,2um

以上

Change Control Notification

Portsmouth, UK, 11 September 2026

260911RCDX-1

Regarding: Discontinuation of ReadyCircuit™ assemblies containing ULTA™ filters

Dear Customer,

As part of the Cytiva change control program, you are hereby informed of the discontinuation of ReadyCircuit™ assemblies containing ULTA™ filters.

Affected products

The product numbers to be discontinued are listed in **Appendix 1**. Additionally, all affected products to which you are registered are listed in the body of the email delivered with this notification.

The affected parts are manufactured at the following site:

- Cytiva US LLC – Duncan, South Carolina, USA

Change description

As part of portfolio management, Cytiva has performed a review of the filtration portfolio. This review identified filter products with redundant technologies and sizes. To streamline internal resources and provide the highest quality filters to customers, ReadyCircuit assemblies containing the ULTA product line will be discontinued. Customers who buy the assemblies listed in **Appendix 1** can use the suggested replacement assemblies or reach out to their account manager or regional sales office to determine the best filter product line for their needs.

Reason for the change

As part of portfolio management, Cytiva has made a strategic business decision to discontinue specific redundant assemblies across its filtration product lines.

Impact of change

Customers can continue to place orders until the implementation date. However, any order placed after this notification is sent will be subject to review to determine whether it can be filled.

Customers using the existing ReadyCircuit assemblies with alternatives listed in **Appendix 1**, can use the newly designed systems which use the same filter medias and have the same functionality.

Customers using the existing ReadyCircuit assemblies with no alternatives listed should contact their account manager or regional sales office for alternate standard or custom filters to suit their needs.

Other filter product lines are not impacted by this notification. There are no plans for additional discontinuations at this time.

Implementation of change

The product numbers in **Appendix 1** will be discontinued on 11 September 2027. All affected assemblies will no longer be available after this date.

Sincerely,

Signed by:

197241612AB84FD...

Joanne Ridgley

Quality and Regulatory Support Manager

Any questions regarding the content of this notification or CCN subscriptions?

Please raise a customer request via: [Contact Us](#)

Cytiva and the Drop logo are trademarks of Life Sciences IP Holdings Corp. or an affiliate.

For additional information on trademarks see cytiva.com/trademarks.

© 2026 Cytiva

Appendix 1:

Discontinued Part Number	Replacement Part Number
12410058	8090-2122M
12410059	8090-2122N
12410060	8090-2122N
12410061	8090-2122N
12410062	8090-2122Q
12410063	8090-2122R
12410064	8090-2122S
12410065	No direct replacement currently available, Contact your account manager or regional sales office to determine the best filter product line for your needs.
12410066	
12410067	
12410068	
12410069	
12410070	
12410071	
12410072	
12410073	
12410074	
12410075	
12410076	
12410077	
12410078	
12410079	
12410080	
12410081	
12410082	
12410083	
12410084	
12410085	
12410086	
12410087	
12410088	
12410089	
12410090	
12410091	
12410092	
12410093	8090-2081V
12410094	8090-2033T
12410095	8090-2033U
12410096	8090-2033V
12410097	8090-2033W

12410098	8090-2033X
12410099	8090-2033Y
12410100	8090-2081V
12410101	8090-2033T
12410102	8090-2033U
12410103	8090-2033V
12410104	8090-2033W
12410105	8090-2033X
12410106	8090-2033Y
12410245	No direct replacement currently available, Contact your account manager or regional sales office to determine the best filter product line for your needs.
12410246	
12410247	
12410248	
12410251	
12410252	
12410253	
29096239	
29096772	
29096785	
29096794	
29096798	
29096802	
29096805	
80590446	
28925793	
KMPHHC9202HH	KA1EKVP6G
KMPHSG9202HH	KA1EKVP6G